



U.S. BASED SUPPORT

HOURS: MONDAY - FRIDAY | 8AM - 5PM EST



1.410.840.3555



support@iagperformance.com



VIDEO INSTRUCTIONS

<https://www.youtube.com/watch?v=2CaI0rVV9eM>





IAG Billet Clutch Fluid Cap For

02-14 WRX, 04-14 STI,

05-09 Legacy GT, 04-08 Forester XT

IAG Billet Clutch Fluid Cap

Part Number: IAG-ACC-5303

Congratulations on the purchase of your Clutch Fluid Cap, and thank you for choosing IAG Performance! These instructions are intended for users with basic mechanical skills. Professional installation is not required.

Product includes:

- 1 IAG Clutch Fluid Cap**
- 2 Decorative Cap Insert**



Tools Needed:

- Pocket Screwdriver
- Silicone Lubricant (Recommended)



Scan Me



Step 1: Remove the factory clutch cap from the Clutch Fluid Reservoir.



Step 2: Using a pocket screwdriver, remove the seal from the factory cap. Carefully pry up seal, do not damage.



Step 3: Prepare the IAG Clutch Cap. Install factory seal onto cap. Line up notches of seal and Cap.



Step 4: Press factory seal into the Clutch Cap, then rotate clockwise to lock seal in place.



Step 5: Install the IAG Clutch Cap onto the Clutch Fluid Reservoir.



Step 6: Prepare the Decorative Cap. Recommend applying a silicone lubricant to the O-Ring.



Step 7: Align the Decorative Cap to the Clutch Cap. Choose desired side to be displayed.



Step 8: Press the Decorative Cap into the Clutch Cap using even pressure. Ensure the insert is fully seated.



If you have any questions about the installation or product please contact support@iagperformance.com or call 410-840-3555